

List of SPC Playground Equipment				Dated 28th November 2022 - V1	
Fletchers Croft	Issue	Risk	Actions required following June 2022 Wicksteed Inspection	Action still to be completed since inspection	manufacturer
Chair Spinner	Play surface edge	Moderate	Play surface edging gap needing attention	Play surface edging gap needing attention	Creative play
See Saw	Play surface edge	low	Play surface edging gap needing attention	Play surface edging gap needing attention	Creative play
Rocking dog	None	Very low	None	none	Creative play
Surface/grass	None	Very Low	None	none	Creative play
Multi Play bridge	Rough/splintered timber	Low	Play surface edging gap needing attention and timber needs attention	Play surface edging gap needing attention and timber needs attention	Creative play
Rocking Duck	foot grip rotate	Low	Tighten rotating foot rest	Tighten rotating foot rest	Creative play
Wet Pour	Play surface edge	Moderate	Play surface edging gap needing attention	Play surface edging gap needing attention	Creative play
Litter Bin	Bin Liner loose	low	Secure bin to floor	Secure bin to floor	Creative play
Picnic tables	fire damage	Very Low	Monitor to see if there is further deterioration	Monitor to see if there is further deterioration	SPC
Gate	Gap less the 12mm	Low	check gate gap	repair gate	Wicksteed
1 Bay 2 swings (Cradle)	Play surface edge	Moderate	Play surface edging gap needing attention	Play surface edging gap needing attention	Creative play
1 bay 2 swings (flat)	None	very Low	None	None	Creative play
Train	finger entrapment	very low	Finger entrapment appearing	Monitor to see if there is further deterioration	Creative play
play panel	None	Very Low	None	None	Creative play
Bench	surface eroded	Low	reinstate surface	reinstate surface	SPC
Fence	None	very low	None	None	SPC
sign	None	Very low	None	None	SPC
Memorial Playing Field	issue	risk	Actions required following June 2022 Wicksteed Inspection	Action still to be completed since inspection	manufacturer
Over Head Rotator	Signs of wear	Moderate	Check bearings and play surface	Check bearings and play surface	Wicksteed
1 bay 2 swings (flat)	Replace seat + surface	Low	Seat to be replaced and surface needs attention	Seat to be replaced and surface needs attention	unknown
Rotating net	Play surface	Moderate	Play surface edging gap needing attention	Play surface edging gap needing attention	Wicksteed
Basket swing	Bolt caps missing	Very Low	Replace bolt caps	Replace bolt caps	Creative Play
Rocking & Cross equipment	Signs of wear / surface	Low	Play surface edging gap needing attention	Play surface edging gap needing attention	Big Toys
Gates to park	slow gate closure	Low	Gate closing too quickly - try to slow	Gate closing too quickly - try to slow	wicksteeds
Bench seats	Surface, fixings loose	Low	Check and tighten fixings, surface build up and treat wood	Check and tighten fixings, surface build up and treat wood	SPC
Parallel Bars	None	Very Low	None	None	Fawns Recreational
1 bay 2 swings (Cradle)	Seats are close to the frame	Low	Monitor seat and frames . Repair play surface	Monitor seat and frames . Repair play surface	big Toys
Somersault bars	Timber checks	Low	Paintwork and timber surface to be treated, smoothed and painted	Paintwork and timber surface to be treated, smoothed and painted	wicksteed
Shelter - gazebo	Fixings/graffiti	Low	Check loose fixings and remove graffiti + eroded surface	Check loose fixings and remove graffiti + eroded surface	unknown
Balance beam	surface erosion, splintering	Low	Monitor splits and treat	Monitor splits and treat	wicksteed
Slide Unit	Rope, graffiti & corroded steels	Moderate	Monitor rope damage, remove graffiti, treat steel uprights and paint	Monitor rope damage, remove graffiti, treat steel uprights and paint	unknown
Multi play - senior	None	Low	Fix top right climbing wall fixing	Fix top right climbing wall fixing	wicksteed
Sign	None	Very Low	None	None	
Fence	Monitor minor damage	Low	Monitor for any further damage or deterioration	Monitor for any further damage or deterioration	SPC
MUGA	Signage & surface	Low	Signage required and monitor & repair surface	Signage required and monitor & repair surface	Wicksteed
Boulders	None	Very Low	None	None	Unknown
Spinning Pole	Signs of wear	Low	Check bearings	Check bearings	Wicksteed
Log Walk	None	Very Low	None	None	Unknown
Litter Bin	None	Very Low	None	None	SPC

Chandlers Way	issue	risk	Actions required following June 2022 Wicksteed Inspection	Action still to be completed since inspection	manufacturer
1 Bay 2 swings (cradle and flat)	bush housing showing wear	very low	Bush housing showing signs of wear	Monitor for further deterioration	unknown
Fence	loose slat	low	Slat to be repaired	Slat to be repaired	spc
Play Surface	Algal growth	low	There is algal or moss growth on the surface resulting in slippery conditions	Clean and treat appropriately	SPC
Benches	Timber rough & splintered	low	Timber rough and splintered	Remove all rough or sharpe edges	SPC
Waste bin	split on lid	low	monitor damaged lid & cut back foliage	monitor damaged lid & cut back foliage	SPC
Gate	Widen gap as is snagging	low	Gate snagging on the surface & gap on side to be widened	Gate snagging on the surface & gap on side to be widened	SPC
Hedge	None	very low	none	none	SPC
Sign on gate	None	very low	none	none	SPC
South Ash	issue	risk	Actions required following June 2022 Wicksteed Inspection	Action still to be completed since inspection	manufacturer
Path way surface	Debris	low	Remove debris from surface	Remove debris from surface	unknown
Multi Play	Remove weeds	low	Remove weed growth on play surface	Remove weed growth on play surface	unknown
Ground surface	None	Very low	None	None	unknown
1 bay 2 swings	None	Very low	None	None	unknown
Litter Bin	None	Very low	None	None	SPC
Bench seat	Re paint	low	Surface requires attention - treat rust and repaint	Surface requires attention - treat rust and repaint	SPC
Fence Bow Top	none	Very low	None	None	unknown
Fence Timber	Leaning Fence	low	Fence leaning slightly again - monitor	Fence leaning slightly again - monitor	Spc and adjoining land
Gate	None	Very low	None	None	unknown
sign	None	Very low	None	None	spc
Abbey Road	issue	risk	Actions required following June 2022 Wicksteed Inspection	Action still to be completed since inspection	manufacturer
Pathway	None	very low	None	None	unknown
Safety surface tiles	Algal growth	low	There is algal or moss growth on the surface resulting in slippery conditions	Clean and treat appropriately	unknown
1 bay 1 swing	Chain Wear and seat with long screws	Low	There is some notable evidence of chain wear	Monitor for any further deterioration and replace when 40% worn	unknown
Seat	Algal growth	low	There is algal or moss growth on the surface	Clean and treat appropriately	unknown
bin	none	very low	None	None	HDC
fence	none	very low	None	None	unknown
gate	none	low	The gate is closing too quickly (less than 4 seconds)	Take corrective action to ensure that the gate closes in 4-8 seconds	unknown
Multi play	none	low	The height of the bridge barrier(s) is insufficient and fails to meet the requirements of BS EN 1176 Part 1 and for head and neck entrapment in the barriers and grabrails	Monitor - No remedial work recommended	unknown
Hedges/bushes	overgrown	very low	None	None	
Normans Way	issue	risk	Actions required following June 2022 Wicksteed Inspection	Action still to be completed since inspection	manufacturer
Basket Ball Goal	Graffiti	very low	Remove graffiti	Remove Graffiti	unknown
Safety surface - tarmac	Algal growth	Moderate	There is algal or moss growth on the surface resulting in slippery conditions	Clean and treat appropriately and clear overhanging foliage and weeds	unknown
gate	snagging & locking mech	Moderate	Carry out remedial works and fit new latch or drop bolts	Carry out remedial works and fit new latch or drop bolts	unknown
Sign	New sign required	Moderate	Provide new sign	Provide new sign	HDC
fence	leaning & damaged	Moderate	Repair as required	Repair as required	unknown