

S. K. SERVICES

Control System Engineers
HVAC Specialists
Building Services
Oil Tank Replacements
Parts

08/05/18



Ref, .Steyning Changing rooms,.

Dear John,

After our recent visit to check the hot water system, we would recommend the following works are carried out to bring it back to good working order.

We have pleasure in quoting for the following works.

1. Supply & install new replacement 12 kw Electric Boiler.
2. Supply & install new replacement control valve & head.
3. Supply & install one new replacement Expansion vessel.
4. Supply & fit tamper proof lockable cover to thermostat.
5. Drain and isolate one cylinder.

Cost for these works would be £1946.00 + vat.

If you have any queries please do not hesitate to contact me, assuring you of our best attention at all times.

S K Services